

## DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DAT	E: 7/14/15	
WEATHER:	73°F, Overcast	
INSPECTED BY: D. Wat K. Honza		

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	Y	0855 hrs. Standing water behind sardbags and
Erosion	N	M	along princh of and small amount standing such
Low Point, B dike*			
Flow	Ν	N	0859 hrs. No Standing water behind cardboxs.
Erosion	N	N	0859 hrs. No standing water behind sandbaggs.  Rio ray and sanabays in Nace.
Outfall			
water surface El.			0902 hrs. Standing water behind sandbags and concrete weir structure. Slow seep Into veir. 23 2".
(top of stoplogs to water)			Mily Humans. 2000 reel 1410 peter. \$3.3.

\* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): fairful lunt ending ~2000 or 7113/15. Studing water at the base of the slope between A and 0 pard.

O 30" rain.

High Time 1847 his low Tide 1241 hrs

